



*FIG. 1*



*FIG. 2*






Figure 4: UV-VIS spectra comparison of cerivastatin released from EVA film and pure cerivastatin in deionized water




Figure 5: Cerivastatin release profile from EVA film wrapped on a stent




Figure 6: Cerivastatin release profile from polycaprolactone wrapped on the stent.

Figure 7: Release of cerivastatin from silicone coated stent




Figure 8: Release of cerivastatin from liquid vitamin E carrier

